

F. H. FOSTER, D. J. WHITE & R. HOLMAN.

Wood Lathe Safety

No. 303,954.

Patented Aug. 26, 1884.



- Wear safety glasses or face shield.
- Avoid loose fitting clothing.
- Tie long hair back or tuck in a cap.
- Turn material over by hand before starting machine.
- Hold turning tools securely on tool rest.
- Use slower speed until piece is balanced.
- Exercise caution with material that has cracks, splits, bark or knots.
- Make sure material is fastened securely in chuck.
- Remove chuck key immediately after using it.
- Keep tools sharp, never force a dull tool to cut.
- Remove tool rest before sanding or polishing.
- Keep your eyes on the job, don't look away while cutting.
- Don't leave lathe running unattended.
- Keep the area around the lathe free of debris.

Witnesses:

Geo. Hellier
H. R. Jordan

Inventors:
Frank H. Foster
Davis J. White

Poster by SawdustMaking.com ©

By their attorney R. H. French